

FIG. 1 - Prior Art






FIG. 2 - Prior Art

# Replacement sheet

2/3



where  $H_1, H_2, H_3, \dots, H_m$  are given by:

$$H_i(z) = \frac{1 - az^{-1}}{1 - bz^{-1}}$$

$|a|$  and  $|b|$  are  $< 1$   
 $a$  and  $b$  have the same sign

OR BY

$$H_i(z) = \frac{1 - 2g_i \cos(P_i)z^{-1} + g_i^2 z^2}{1 - 2r_i \cos(P_i)z^{-1} + r_i^2 z^2}$$

FIG. 4

# Replacement Sheet

3/3




FIG. 5